

Technical Oversight Committee
May 18, 2010

Construction and Maintenance Impacts on Monitoring

Pete Rawlik

Sr. Environmental Scientist,
Restoration Sciences Department

S39 Maintenance Underway




Monitoring temporarily moved 0.05 km upstream



Tamiami Trail Bridge

construction has closed 4 out of 10 culverts to sampling Tambr 2, 3, 4 & 5



S333

S334

41

Culvert monitoring
part of PIN




Tambr 105
Turbidity curtain in place;
Concrete pads being poured
to the east and west



Currently no impacts to sampling

S150

- Planned maintenance coming soon
- Impacts on sampling are being investigated



STA2



STA3/4

WCA2A

G371

S7

S150

27

WCA3A

2009 Palm Beach County Aerial Photography

© 2007 Google™

Questions

