


Add-on Items #76 & #77

Stormwater Treatment Area 1 East Emergency Actions at S-375



STA 1 East / S-375





S-375 Initial Actions

- March – Sink holes found
- Pre-cast culverts settled & misaligned
- Potential for structure failure
- Initial actions to assure flows
 - Dive team repairs one culvert
 - Field crews install four 42 inch temporary pumps with diesel engines, fuel tanks and pipes.



SOUTH FLORIDA WATER MANAGEMENT DISTRICT



S-375 Repair / Replacement

- Install sheet pile or earthen coffer dam to dewater S-375 for inspection by SFWMD & USACE
- Prepare forensics report on failure, with recommendations for permanent repairs
- Complete design details to repair or replace S-375
- Expedite procurement, solicitation, award and start of construction contract
- Complete construction of repairs or replacement



Emergency Order Item #77

Enter an Emergency Order regarding repair of Structure S-375; providing as effective date.



RESOLUTION Item #76

A RESOLUTION OF THE GOVERNING BOARD OF THE SOUTH FLORIDA WATER MANAGEMENT DISTRICT AUTHORIZING THE EXECUTIVE DIRECTOR TO PROCURE GOODS AND SERVICES PURSUANT TO THE GOVERNING BOARD'S EMERGENCY ORDER TO REPAIR THE S-375 STRUCTURE, PROVIDING AN EFFECTIVE DATE.

