

HILLSBORO CANAL BANK STABILIZATION PROJECT

Before and after construction just east of Lyons Road in Coconut Creek



The exposed gray mats you see in the “after” photos are the result of very low water levels; concrete blocks are not used. The mats will be hidden when the new sod has grown and water levels are normal.