



L-31N Updated Monitoring Program

New wells and dataloggers
have been installed




Paired Monitoring Wells ▲ Flowmeters ■

Water Level Difference Across Seepage Barrier



Water Level Difference Across Seepage Barrier



Dade-Broward Levee Project

Task 1: 7.5 mile berm repair
completed 2016

Task 2: two proposed water control structures
Notice to Proceed issued

Task 3: L-30 structure repair/
remote control operation
in design

FY17 Funding Request

Will present to the Committee
once the Task 3 design/review/
cost estimate are completed

